














<p><b>A X1</b></p>  <p>M6X45</p>	<p><b>B X4</b></p>  <p>M6X50</p>	<p><b>C X1</b></p> 	<p><b>D X1</b></p> 	<p><b>E X1</b></p> 
<p><b>F X1</b></p> 	<p><b>G X5</b></p>  <p><math>\phi 14 * \phi 6</math></p>	<p><b>H X4</b></p>  <p><math>\phi 10 * \phi 6.5</math></p>	<p><b>I X1</b></p>  <p>M5</p>	


1



2



3



4

